



Boat-ramp on shore: The **topsoil** (1 to 2.5 meters below the ground level) is heavily contaminated with; barium, copper, lead and zinc.



Boat-ramp waterside: Mineral oils have also been found in the **water** at the boat ramp, some of which have since been re-mediated.